

EXHIBIT 3

CAPTAIN'S REPORT

of the

TUG MACKENZIE ROSE INCIDENT

In the Matter of COEYMANS MARINE TOWING, LLC d/b/a CARVER MARINE TOWING as Owner and Operator of M/T MACKENZIE ROSE, (IMO No. 8968765), her cargo, engines, boilers, tackle, equipment, apparel, and appurtenances, etc., IN REM, ("M/T MACKENZIE ROSE"), petitioning for exoneration from or limitation of liability in allision with Norfolk and Portsmouth Belt Line Railroad Company Main Line Railroad Bridge (the "Bridge") occurring June 15, 2024 in and about the Elizabeth River, Virginia.

**UNITED STATES DISTRICT COURT
EASTERN DISTRICT OF VIRGINIA: NORFOLK DIVISION
Case No. 2:24-cv-00490**

RFI File No. 25FE0014

Prepared By:

CAPTAIN NICHOLAS J. LEWIS

July 2, 2025

TUG MACKENZIE ROSE INCIDENT

CAPTAIN'S REPORT

July 2, 2025

A. INTRODUCTION

On June 15, 2024, the Tug Mackenzie Rose, pushing ahead the deck barge Weeks 281, was transiting northbound on the Elizabeth River, Southern Branch, Virginia. During the transit, the tug/barge allided with the Norfolk and Portsmouth Belt Line Railroad Company Main Line Railroad Bridge. The Bridge was damaged as a result of the allision.

The purpose of my investigation was to determine if the actions/inactions of the Captain aboard the Tug Mackenzie Rose and the owners of the tug, Coeymans Marine Towing, LLC and Carver Marine Towing, LLC (hereinafter "Coeymans," "Carver"), created unreasonably dangerous conditions that caused the allision with the Bridge.

My investigation into this matter and the preparation of this report was performed at the request of Mark C. Nanavati, Esq. of Sinnott, Nuckols & Logan, P.C., 13811 Village Mill Drive, Midlothian, Virginia 23114.

B. QUALIFICATIONS

I am a graduate of the State University of New York, Maritime College at Fort Schuyler, with a Bachelor of Science degree in Marine Transportation.

I have more than 30 years in the marine industry, both at sea and ashore. I am a retired licensed U.S. Coast Guard Master of Steam and Motor vessels of not more than 1600 gross tons upon oceans and a 3rd Mate of Steam and Motor vessels of any gross tons upon oceans. I have been a Captain for more than 25 years on tug and barge ocean-going units. I also worked as a 3rd Mate aboard ocean-going tankers.

As the Captain of the vessel, I was responsible for the overall operation of the vessel, including the safe navigation, and mooring of the vessel, compliance with all safety policies and procedures; including vessel security and ensuring that all vessel maintenance schedules were up to date. I was responsible for all aspects of the operation: budget planning, purchasing of stores, spare parts, safety equipment, electronics, fuel, as well as crews' payroll and overtime.

As Captain and Mate aboard ocean tankers and tanker barges, I was responsible for developing critical vessel onboard procedures and protocols to comply with company policies. This included writing procedures for oil and cargo transfers as well as an operation manual for all tasks done aboard the vessel. I was also responsible for all vessel inspections, audits, onboard injury investigations and analysis.

My CV outlining my complete education, experience and training is attached separately.

TUG MACKENZIE ROSE INCIDENT

The approach taken for the analysis of this investigation is based on reliable scientific reasoning and methodology which is accepted by the scientific community. All my statements, findings, analysis, and opinions contained herein are stated within a reasonable degree of professional certainty. They are based on my education and over 30 years of experience in the marine industry and are subject to change if additional information becomes available.

Testimony as an Expert

A document listing each of the occasions on which I have given expert testimony in the past 4 years is attached separately.

Exhibits

I reviewed and may use the following materials as exhibits to illustrate testimony: all references and documents cited in this report or listed as Materials Available for Review.

C. AVAILABLE INFORMATION

1. Complaint for Exoneration from or Limitation of Liability (Filed 8/08/2024).
2. Answer of Evanston Insurance Company a/s/o Norfolk and Portsmouth Belt Line Railroad Company, to the Petition for Exoneration from or Limitation of Liability (Filed 12/05/2024).
3. Claim of Evanston Insurance Company a/s/o Norfolk and Portsmouth Belt Line Railroad Company (Filed 12/05/2024).
4. Carver Rule 26(a)(1) Initial Disclosures
5. Coeymans' Initial Production (000253-000705)
6. NPBL Initial Production (000001-000211)
7. US Coast Guard Form 2692,
8. Rosepoint and Logbook Data
9. Master's Daily Reports
10. Near Miss, Incident Reports and JSA's (Carver ESI 000020-000037)
11. Responses & Objections to #101618597v4 Plaintiff's First Set of Discovery Requests – Page 2
12. Carver's First Supplemental Answers to Belt Line's First Set of Interrogatories
13. Carver Marine's Third Supplemental Response to the Belt Line's First Requests for Production of Documents and Things
14. Norfolk - Carver Production for Third Supplemental Response to RFPs
15. NPBL's First Supplemental Responses to Coeymans' Requests for Production
16. NPBL Supplemental Production
17. Response to Norfolk and Portsmouth Belt Line Railroad Company's Second Set of Requests for Production of Documents
18. Response to First Requests for Production of Documents and Things
19. Answers to Norfolk and Portsmouth Belt Line Railroad Company's First Set of Interrogatories

TUG MACKENZIE ROSE INCIDENT

20. NPBL000201-2024-06-15, Allision Event Surveillance Vidéo 1
21. Norfolk and Portsmouth Belt Line Railroad Company's Responses to Petitioner's Second Requests for Production of documents
22. Brian Moore Deposition and exhibits, April 28, 2025.
23. Leonard Baldassare Deposition and Exhibits, April 29, 2025.
24. Jarkeis Jamal Bass Morrissey Deposition, April 30, 2025.
25. Sharif Porter Deposition, April 30, 2025.
26. Carver/Nicholas Laraway Deposition and Exhibits, June 17, 2025
27. Jason McGrath Deposition and Exhibits, June 18, 2025

D. DESCRIPTION OF THE INCIDENT

On June 15, 2024, Captain Morrissey (Morrissey) was steering the Tug Mackenzie Rose (Tug) on autopilot without a designated lookout while transiting north on the Southern Branch of the Elizabeth River, Virginia. The Tug was pushing ahead a 200-foot unmanned deck barge, Weeks 281 (Barge), owned by Weeks Marine.

The Tug/Barge (Unit) was in the channel heading for the center of the Norfolk and Portsmouth Belt Line Railroad Company Main Line Railroad Bridge (Bridge). The Bridge was in the up position to allow for clear passage to any marine traffic on the River. As the Unit was approaching the Bridge, it veered hard to port (left), causing the Unit to go out of the channel towards the west side of the Bridge. At that location, the Bridge is a fixed structure just a few feet above the River with no lift for the Unit to clear underneath the Bridge.

The speed of the Unit was approximately 5.2 knots as the Unit approached the Bridge. The video: NPBL000201-2024-06-15, Allision Event Surveillance Video 1 shows the Barge hitting the Bridge after which the structure can be seen rocking hard back and forth. After the allision with the Bridge, Morrissey backed the Tug full astern, maneuvering the Unit all the way back into the channel and then proceeded to go ahead and pass under the open Bridge.

The Captain on watch, steering the Tug, James Morrissey's statement of the incident follows:

June 15, 16:59: Statement that happened approximately 16:30 with the Nort and PBL RR Bridge.

*I, James Morrissey, was operating outbound in Norfolk VA southern branch of the Elizabeth river with the barge weeks 281. The Tug experienced a steering malfunction causing the tug and barge to turn to port and touchup on the bridge before it could be corrected. No Damage to the barge and no visible damage to the bridge.
Captain James Morrissey.*

TUG MACKENZIE ROSE INCIDENT

I anticipated more would be learned from his deposition on that was noticed for June 24, 2025, but he failed to appear to testify. Captain Morrissey, in command of the Unit, completely disregarded all safe practices of good seamanship and navigation. He negligently¹ and recklessly² deviated outside the navigational channel, and without cause proceeded ahead at a speed of approximately 5.2 knots until the Unit allided with the western side of the fixed portion of the Bridge.

E. BACKGROUND

The Norfolk and Portsmouth Belt Line Railroad Company is the owner of the Bridge, which crosses the southern branch of the Elizabeth River between the cities of Chesapeake and Portsmouth, Virginia. The bridge is a single-track railroad vertical lift bridge and remains in an open position such that vessel traffic may pass underneath it, except when lowered to allow trains to pass.

See 33 C.F.R. § 117.997:

117.997 Atlantic Intracoastal Waterway, South Branch of the Elizabeth River to the Albermarle and Chesapeake Canal.

(a) The draw of the Belt Line Railroad Bridge, mile 2.6, in Portsmouth and Chesapeake will operate as follows:

(1) The bridge will be left in the open position at all times and will only be lowered for the passage of trains and to perform periodic maintenance authorized in accordance with subpart A of this part:

(4) When the bridge closes for any reason, the controller will announce 30 minutes in advance, 15 minutes in advance, and immediately preceding the actual lowering, over marine channel 13, that the Belt Line Railroad Bridge is closing for river traffic. In each of these three announcements, the bridge/train controller will request all concerned river traffic to please acknowledge on marine channel 13.

¹ Negligent: a. marked by or given to neglect especially habitually or culpably; b. failing to exercise the care expected of a reasonably prudent person in like circumstances. (Merriam-Webster.com Dictionary, s.v. "negligent," accessed July 2, 2025. <https://www.merriam-webster.com/dictionary/negligent>

² Reckless: marked by lack of proper caution : careless of consequences. (Merriam-Webster.com Dictionary, s.v. "reckless," accessed July 2, 2025. <https://www.merriam-webster.com/dictionary/reckless>

TUG MACKENZIE ROSE INCIDENT

Tug Mackenzie Rose Crew Matrix on June 15, 2024:

Captain Christopher Lee Miller

Captain/Mate James Dominick Morrissey

Deckhand Sharif Porter

Deckhand Jarkeis Jamal Bass Morrissey

Engineer Jason McGrath

June 15, 2024, Mackenzie Rose logbook entry

Incident - Norfolk, VA - Mate James Morrissey reports the auto pilot was not completely turned off he was able to correct and switch back over to hand steering and begin backing on the Weeks 281 Barge and maneuvered the barge alongside fendering on the North and PBL RR Bridge, photo taken. proceed slowly away from bridge.

This entry omits any information that the Unit plowed directly into the Bridge. The point of impact was on the west side of the fendering, outside the channel. The video shows the Tug moving ahead at over 5 knots when the barge hit the structure of the Bridge, where the west side trestle was located. It also shows the trestle rocking back and forth, several times, after the impact. Due to the allision, the railroad tracks were shifted out of alignment. This caused the Bridge to be shut down to all train traffic in either direction.

F. ANALYSIS

Based on my training and experience and the documents reviewed, crew statements, vessel logs, USCG 2692 form, and applicable regulations, it is my expert opinion that several navigational, procedural, and managerial failures contributed to and caused the subject hit and run allision.

The Officer of the Watch (OOW), Captain James Morrissey, was using autopilot when he should have been manual steering. This error directly resulted in the tug and barge veering to port, outside the safe channel, leading to the allision with the bridge.

When operating a tug/barge unit in a narrow channel it is imperative to use good seamanship and to operate in a safe and prudent manner. The OOW should be controlling the rudder with manual steering, not autopilot. The Coeyman's Tug Safety Management System (TSMS) does not prohibit the use of the autopilot in restricted conditions such as bridges or busy waterways like the Southern Branch.

TUG MACKENZIE ROSE INCIDENT

Carver's General Manager, Brian Moore confirmed under oath that there was no policy restriction on autopilot use in the Elizabeth River. This represents a significant lapse in safety oversight by vessel management. B. Moore Deposition: 281: 17-23:

17· There was no prohibition -- Carver
18· ·didn't prohibit the captain from using the auto pilot
19· ·system in the transit that he was making, you know,
20· ·down the southern branch of the Elizabeth River
21· ·before the allision?

22· . . . A· . . No. It's up to the captain's discretion

23· ·to make that judgment call.

The Coeyman's Tug Safety Management System (TSMS) documentation had no explicit policy, specific prohibition or procedural control for autopilot use near bridges or in confined waters. This lack of procedural guidance allowed the captain to rely on personal discretion, contrary to industry best practices and standards.

In addition, the use of autopilot in confined inland waterways, particularly when approaching a fixed structure such as a railroad bridge, violates best practices and specific warnings found in the Simrad AP70MK2 Autopilot Manual Chapter 2: (The Autopilot used in the upper wheelhouse on the Tug Mackenzie Rose at the time of the allision.)

Basic operation

Safe operation with the autopilot

Warning: An autopilot is a useful navigational aid, but DOES NOT replace a human navigator.

Warning: Ensure the autopilot has been installed correctly, commissioned and calibrated before use.

Do not use automatic steering when:

- **In heavy traffic areas or in narrow waters**
- In poor visibility or extreme sea conditions
- When in areas where use of an autopilot is prohibited by law

When using an autopilot:

- **Do not leave the helm unattended**
- Do not place any magnetic material or equipment near the heading sensor used by the autopilot system
- Verify at regular intervals the course and position of the vessel
- **Always switch the autopilot to standby and reduce speed in due time to avoid hazardous Situations.**
- **Verify at regular intervals the course and position of the vessel.**

TUG MACKENZIE ROSE INCIDENT

This shows a complete lack of prudent management on Carver's part in operating a vessel safely in a close quarters/narrow channel situation. Carver deprived the Norfolk and Portsmouth Belt Line Railroad Company protections afforded by the autopilot manufacturer which created unseaworthy conditions aboard the Mackenzie Rose and was a cause of the allision.

Industry practice and standards, as well as my own experience as a tugboat captain with three different tugboat companies, Sun Transport, Maritans, and Exxon Shipping Co/SeaRiver Maritime, prohibits navigating a vessel using autopilot in any narrow river, channel, or when transiting a bridge.

Prudent seamanship also dictated that a lookout should have been used for the transit when approaching the Bridge, even in daylight.

33CFR-83.05 - US Inland Rules of the Road: Rule 5 Look-out states:

"Every vessel shall at all times maintain a proper look-out by sight and hearing as well as by all available means appropriate in the prevailing circumstances and conditions so as to make a full appraisal of the situation and of the risk of collision."

Key Points of Rule 5:

- Every vessel must maintain a look-out at all times.
- Look-out must use sight, hearing, and all available means (radar, AIS, etc.).
- The purpose is to assess the situation fully and identify risks of collision.
- The quality and method of the look-out must be appropriate to the prevailing circumstances and conditions.

In this case, there was no dedicated lookout assigned while navigating in a confined waterway near a fixed structure, which violates the above rule. The failure to assign a dedicated lookout constitutes a breach of the Inland Rules of the Road and contributed materially to the allision with the Bridge. Based on the information at hand including the limited Daily Masters Reports produced by Carver, Carver did not provide proper supervision, training, management, or oversight regarding decisions related to the posting of a lookout.

Carver contributed and caused this hit and run allision by their lack of training, oversight, and/or management with regards to the transiting of a Bridge, the use of a proper lookout, and allowing a vessel operator to use his/her discretion to steer the vessel on autopilot through a Bridge.

Carver GM B. Moore testified that he didn't know of anyone that was in charge of training the crews aboard Carver's vessels. B. Moore Deposition: 108:22-24, 109: 2, 12-21:

108

22...Q...So there isn't anybody that you know of

TUG MACKENZIE ROSE INCIDENT

23· that has training responsibility at Carver Marine
24· Towing?
109
·2· . . . A· . . . Not directly assigned a training spot. *DH*
12· . . . Q· . . . At Carver Marine Towing, is there
13· somebody that uniquely has the responsibility for
14· training new hires?
15· . . . A· . . . The master or mate, whoever that signs
16· them off in within Helm as -- and appropriate to
17· stand watch.
18· . . . Q· . . . And does the master or mate that has
19· that responsibility also receive training in what
20· they're supposed to train the deckhands in?
21· . . . A· . . . I don't know.

Carver had no designated safety officer for the fleet to oversee all crew training and new hire training before the allision. It was not until after the subject allision that Mr. Jason Galioto was designated as the marine safety and compliance person to handle vetting for the fleet. (He had been hired as a logistics coordinator trainee (Dispatcher) and it is unknown what his experience or expertise is.) He worked directly for the Carver GM, B. Moore.

Notification of the USCG is mandatory after a marine casualty as stated in 46 C.F.R. § 4.05-1:

4.05-1 Notice of marine casualty.

(a) Immediately after the addressing of resultant safety concerns, the owner, agent, master, operator, or person in charge, shall notify the nearest Sector Office, Marine Inspection Office or Coast Guard Group Office whenever a vessel is involved in a marine casualty consisting in—

(1) An unintended grounding, or ***an unintended strike of (allision with) a bridge;***

46 CFR 4.05.1 mandates immediate notification of a marine casualty. In this case, the allision with the Bridge was not promptly reported to the Coast Guard, delaying investigation and post-incident drug and alcohol testing.

Despite crew claims of minimal impact, photographs, and video of bridge structure movement document otherwise. Variance in post-incident reports and a lack of timely Coast Guard notification further undermine the reliability of the crew's account and created potentially life-threatening conditions for the Norfolk and Portsmouth Belt Line Railroad Company and the public at large.

This is a direct result of lack of training on reporting and an over-reliance by Carver on requiring the crew to report first to the company any incidents, allowing the company to maintain control over what is reported to the Coast Guard and when it is reported, if at all. Though the photograph taken by a crew member with the camera on the Tug is grainy, it shows that the bridge structure was completely shifted out of alignment at the time the Tug was passing through the channel under the bridge. For Carver to

TUG MACKENZIE ROSE INCIDENT

have received this photograph and not immediately inform the Coast Guard of the allision in compliance with reporting and drug and alcohol testing requirements, was irresponsible and contrary to its reporting obligations under the CFR and its own SMS.

On June 15, 2024, after the allision with the Bridge at 1630, all five of the crew members hand wrote a statement about what they were doing when the allision occurred and what had happened. Captain Miller and CE McGrath were the only ones with a signature. (Carver 000047, 000095, 000079, 000086, 000071).

On June 15, 2024, at 1659 a typewritten report was also completed for each crew member. All stated essentially the same information on the written report except for Captain Miller's. His was the same adding that a photo was taken showing no visible damage to the bridge. (Carver 000048, 000094, 000083, 000085, 000070).

There is a third statement typed on Carver Marine Towing Stationary, RE: Incident Report, for all of the Tug crew except Captain Morrissey. There is no date of when these reports were typed. The statements do have the date, June 15, 2024, and time of incident: 1630 listed.

All 4 of the statements from the crew are different from their written and typed reports. There is no more mention of feeling a bump, (Miller), or of the boat coming to an abrupt stop, (McGrath), or feeling the boat hit something, (Ja. Morrissey), or noticed we had landed against the fenders, (Porter). (Carver 000049, 000082, 000084, 000072).

CE McGrath, referring to the Carver Statement in his Deposition states the following:

- 12 Q. All right. But you don't
13 remember either signing that, or?
14 A. I don't even remember seeing
15 this, to tell you the truth.
16 Q. And it sounds like based on
17 what you just described that it's not
18 accurate in terms of your own memory?
19 A. No, sir.

In my opinion, the statements were procured by Carver to justify its failure to immediately report the allision to the Coast Guard as required by CFR 4.05.1.

Carver's Failure to Discipline or Train James Morrissey

On January 21, 2024, Captain Morrissey was at the helm of the Tug Mackenzie Rose, made up to a barge, on the Cooper River in Charleston, South Carolina. At 0835 while docking at Pier K the barge allided with the northside corner of Pier K. The result of the allision was a piling was bent in and the concrete behind

TUG MACKENZIE ROSE INCIDENT

the piling was damaged as well as damage to the barge. A US Coast Guard form 2692 was filled out and submitted to the local USCG station. According to the Carver G.M Brian Moore deposition: 89: 14-17

14· . . . Q· . . Was Captain Morrissey disciplined for
15· ·damaging the South Carolina Port Authority dock in
16· ·January of 2024?
17· . . . A· . . **For that incident, no.**

Concerning the June 15, 2024, allision, according to the Carver GM Brian Moore deposition: 90: 9 - 25

·9· . . . Q· . . To your knowledge, has Captain Morrissey
10· ·ever been disciplined for the incident -- the
11· ·allision with the Belt Line Bridge in 2024?
12· . . . A· . . **He was suspended with pay pending that**
13· ·investigation.
14· . . . Q· . . But was he disciplined?
15· . . . MR. RODGERS:· Objection to form.
16· . . . A· . . **A disciplinary form?· No.**
17· . . . Q· . . I'm sorry?
18· . . . MR. RODGERS:· Asked and answered is my
19· . . ·objection, but you can answer if you understand
20· . . ·his question.
21· . . . A· . . **To me, the suspension was the**
22· ·disciplinary.
23· . . . Q· . . So he still collected full -- collect
24· ·full pay while he was on admin leave, right?
25· . . . A· . . **Yes.**

Captain Morrissey had an allision on January 21, 2024, with the tug Mackenzie Rose, while docking a barge, and did over \$75,000 worth of damage to a pier and barge. Carver Marine Towing management took no disciplinary action against Morrissey at that time.

On June 15, 2024, Captain Morrissey, with the Tug Mackenzie Rose and the barge Weeks 281 had an allision with the Bridge, on the outside of the channel where the bridge was fixed. Carver Marine Towing's discipline was to suspend Morrissey, indefinitely with full pay.

Carver management is irresponsible and deficient when it comes to the safe operation of the fleet and safety of the crews aboard its vessels. By not disciplining Morrissey in the first allision and then suspending him with full pay in the second allision, Carver showed no initiative to ensure that the fleet operates in a safe and proper manner.

TUG MACKENZIE ROSE INCIDENT

Carver Marine knew, or should have known, there had been a problem with the autopilot on the Tug Mackenzie Rose. In May 2024 there were 2 autopilot rudder failures and near misses. On May 3, 2024, the autopilot took a hard left while the tug was towing a barge at sea turning the Tug back towards the barge. The Tug barely missed colliding with the barge. On May 21, 2024, the autopilot once again had a hard over rudder incident and headed the Tug into heavy seas.

The Tug had been having autopilot issues since the beginning of 2024, with numerous near miss incidents. Carver had Ayers and GMT make repairs to the autopilot in March and April of 2024, when the Tug experienced autopilot failures. After both incidents in May, Carver failed to have a technician inspect, check, and/or repair the autopilot after either incident in May. See e.g., Carver Marine's 30(b)(6) June 17, 2025 Deposition (pp 151-154) and Brian Moore's April 28, 2025 Deposition (pp 275-276).

If Carver Marine was a conscientious, reliable, and safe operator of the Tug, they would have had the autopilot inspected and serviced. Knowing the Tug was having autopilot issues, Carver should have prohibited the use of the autopilot until it was repaired or replaced. **By not having the autopilot repaired and not restricting the use of the autopilot, Carver management was a cause of the allision with the NPBL Bridge.**

These failures — navigational, procedural, and managerial — collectively created an unreasonably dangerous situation and an unsafe working environment, directly contributing to the incident.



The Norfolk and Portsmouth Belt Line Railroad Company Main Line Railroad Bridge (NPBL Bridge) is in an open position.

TUG MACKENZIE ROSE INCIDENT



NPBL Bridge damage on June 15, 2024

G. FINDINGS

Within the bounds of reasonable professional certainty, and subject to change if additional information becomes available, it is my opinion that:

1. The unit made direct contact with the bridge, causing visible structural movement (as evidenced by surveillance video), which is contrary to crew statements of “no damage” or “minor impact.”
2. The unit deviated outside the navigational channel without cause and continued forward at approximately 5.2 knots toward a fixed portion of the Norfolk and Portsmouth Belt Line Railroad Bridge.
3. The deck logbook entry was inaccurate and misleading, stating the Unit had maneuvered onto fendering and away from the Bridge when in fact it struck the fixed western structure directly.
4. The Officer of the Watch (Captain James Morrissey) failed to properly disengage the autopilot and did not switch to manual steering (Non-Follow-Up mode) in a confined navigational channel, resulting in loss of directional control.
5. The company TSMS (Tug Safety Management System) lacked policy guidance prohibiting autopilot use in confined waterways or near critical infrastructure, leaving the decision entirely to operator discretion.

TUG MACKENZIE ROSE INCIDENT

6. The use of autopilot in a narrow inland waterway while approaching a fixed railroad bridge was in direct contradiction to established safe seamanship practices and warnings in the Simrad AP70MK2 Autopilot Manual.
7. Carver deprived the Norfolk and Portsmouth Belt Line Railroad Company protections afforded by the autopilot manufacturer which created unseaworthy conditions aboard the Mackenzie Rose and was a cause of the allision.
8. No lookout was posted in violation of 33 C.F.R. § 83.05 (Rule 5 – Look-out), a critical error during confined water navigation in daylight while pushing ahead a barge.
9. The company TSMS (Tug Safety Management System) did not prohibit autopilot use in confined waterways or near critical infrastructure, leaving the decision entirely to operator discretion.
10. Carver gave no official training to its operators with regard to how to safely transit a waterway when approaching a bridge, when a proper lookout should be posted, and had no restrictions on the use of the autopilot.
11. The Coast Guard was not promptly notified of the allision, in violation of 46 C.F.R. § 4.05-1. This delayed official investigation and post-incident drug and alcohol testing, and created potentially dangerous conditions for the Norfolk and Portsmouth Belt Line Railroad Company and the public at large.
12. Post-incident accounts from multiple crew members were inconsistent, with discrepancies in timing, actions taken, and observations.
13. By not having the autopilot repaired and not restricting the use of the autopilot, Carver management was a cause of the allision with the NPBL Bridge.
14. These failures - navigational, procedural, and managerial – singularly or in combination, created an unreasonably dangerous and unseaworthy conditions, that violated well established standards of safe marine practice, and were causes of this allision incident.
15. In my opinion, given the lack of training to the crew, the lack of policies and procedures regarding use of an autopilot or lookout during bridge transits, the known issues with the autopilot, and Captain Morrissey's prior allision, the Tug Mackenzie Rose was unseaworthy. Carver should not have allowed this Tug to sail with this crew.



Captain Nicholas J. Lewis
Marine Expert